



Weekly SuperBooth Maintenance and Cleaning Procedures

- Check to make sure Camera is in focus. [See manual for help.]
- Check printer tray alignments. [Bend the metal tray to align.]
- Empty print cutoff tray. [Remove little strips so the printer doesn't jam]
- Check to make sure buttons are tight.

-
- Use Ammonia-free cleaner to clean both the inside and outside surfaces of the SuperBooth.
 - Use Ammonia-free cleaner to clean the acrylic screens covering the monitors and camera hole.
 - Dust off the top of the SuperBooth.
 - Vacuum the curtain to remove dust and dirt.